

# SAMPLE FOOT DRAWING

## Pendragon Boot Company

step 1

Draw around the foot with ballpoint pen at 90° to the page to make outer line .

step 2

Draw around the foot with ballpoint pen at 45° to the page to make inside line.

Step 3



Measure all the way around the foot with a tape measure at the toes, ball of foot and instep. Mark points measured on foot drawing. Write measurements clearly next to points measured.

Step 7  
Scan and save as PDF and email to us or mail us the original

Step 6  
Measure the lenth of the foot from longest toe to heel and mark on page in centimetres.

Step 4 (For Boots)

Measure up from the ground to your ankle bone and around at this point. eg 10cm - 23cm  
If you are ordering higher boots, measure up and around at 5cm intervals.



Step 5  
For boots - measure around heel to ankle at the widest point.

22cm

23cm

25cm

26cm